

Subject: Checking tightening bolts drag brake discs at the wheel of K-218A-000

Based on the information of the service we ask you to transmit this information to your customers who have installed on the aircraft main gear wheels 8 ", catalog number K-218A-000:

During the first hours of operation may permit drag pivots the brake disc. Is required after the first 5-10 hours of operation, where it occurred immediately, check tightness of bolts drag brake disc - see picture.
During the inspection, it is necessary to insure the threaded pins Loctite 222 (not for model 2009 -).



Jiří Kašpar
OTŘ